

Inspection Photos

API: 071-09420

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/14/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09420 | Date: 9/14/2021

Inspection Photos



Photo 1. Facing west along the access road. The pig launcher receiver has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 9/14/2021

Inspection Photos



Photo 2. Facing along the access road. The noxious weeds along the road are wilted from weed control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 9/14/2021

Inspection Photos



Photo 3. The valve box has been removed. This area of disturbance will need be reclaimed with perennial vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 9/14/2021

Inspection Photos



Photo 4. The pipe riser previously observed was removed. This area of disturbance will need be reclaimed with perennial vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 9/14/2021

Inspection Photos



Photo 5. Facing northwest toward the access road and location that remains per variance request.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 9/14/2021