

Final Reclamation Inspection

September 13, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 333124

Inspection Document #: 697503245

Weld County, CO

NESE Section 20 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SUCCO #43-20
Location ID: 333124



Photo 1. Photo taken from the well location, facing East. Surface owner indicated no crops were likely planted over the wellhead area but will in the future. Operator shall ensure soils are in compliance with Rule 915.b. standards.

Inspection Photos
Location Name: SUCCO #43-20
Location ID: 333124



Photo 2. Photo taken from the wellhead location. Photo illustrates plastic debris.



Inspection Photos
Location Name: SUCCO #43-20
Location ID: 333124



Photo 3. Photo taken from the wellhead location. See comments under Photo 2.



Photo 4. Photo taken from the wellhead location. Photo illustrates concrete debris.