

# Final Reclamation Inspection

September 13, 2021

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 455229

Inspection Document #: 697503247

Weld County, CO

NWSW Section 20 T2N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SPILL/RELEASE POINT  
Location ID: 455229



**Photo 1.** Drone aerial imagery illustrates the approximate extend of stunted crop growth, which is related to Remediation Project #13821.

Inspection Photos  
Location Name: SPILL/RELEASE POINT  
Location ID: 455229



**Photo 2.** Photo taken from within the Remediation Project. Photo illustrates stunted crop growth.



Inspection Photos  
Location Name: SPILL/RELEASE POINT  
Location ID: 455229



**Photo 3.** Photo taken north of the Remediation Project, facing South. Photo illustrates stunted crop growth.

Inspection Photos  
Location Name: SPILL/RELEASE POINT  
Location ID: 455229



**Photo 4.** Photo taken north of the Remediation Project, facing Southwest. See comments under Photo 3.

