


See Figure 6b for the Extent of the Colorado Geologic Survey Data


**Aota Technical, LLC**  
**Twin Bridges Resources LLC**  
**Red Rocks 35-15**  
**Geologic Hazard Map**  
 Las Animas County  
 NW1/4NE1/4 Sec. 35, T29S R55W 6th P.M.  
 Date: 6/25/21  
 Figure No. Figure 6a

- Legend**
- Dry & Abandoned O&G Well
  - Conventional Vertical Helium Gas Well
  - Working Pad Surface (170' x 250')
  - Oil and Gas Location (180' x 260')
  - 1 Mile from Working Pad Surface

- Colorado Geological Survey Landslide Area Data
- Parcel Boundary




Data Source: COGCC GIS Online Colorado Geological Survey



**Aota Technical, LLC**  
**Twin Bridges Resources LLC**  
**Red Rocks 35-15**  
**Geologic Hazard Map**  
 Las Animas County  
 NW1/4NE1/4 Sec. 35, T29S R55W 6th P.M.  
 Date: 6/25/21  
 Figure No. Figure 6b

- Legend**
- Dry & Abandoned O&G Well
  - Conventional Vertical Helium Gas Well
  - Working Pad Surface (170' x 250')
  - Oil and Gas Location (180' x 260')
  - 1 Mile from Working Pad Surface

- Colorado Geological Survey Landslide Area Data
- Parcel Boundary



Data Source:  
 COGCC GIS Online  
 Colorado Geological Survey

**SELF-CERTIFICATION**

I certify that I am qualified according to C.R.S. 23-41-208(1)(b) to have evaluated potential geologic hazards (including avalanche; dam/levee failure; drought; earthquake; erosion and deposition; expansive soils; extreme heat; flood; hail; landslide, mud/debris flow, rockfall (collectively, landslide); lightening; severe wind; subsidence; and tornado) within a 1-mile radius of the proposed Working Pad Surface from data provided by the Colorado Oil and Gas Conservation Commission, Las Animas County Hazard Mitigation Plan, USGS regional geologic mapping, satellite imagery, slope gradient analysis, and a stratigraphic columnar section of the local area. My evaluation meets statutory and regulatory requirements by finding no geologic phenomenon which is so adverse to past, current, or foreseeable construction or land use as to constitute a significant hazard to public health, safety, or to property.



Kurt Constenius, Ph.D.  
8790 N. Shadow Mountain Dr.  
Tucson, AZ 85704

6/14/2021

Date