

Final Reclamation Inspection

September 13, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320309

Inspection Document #: 697503249

Adams County, CO

SWSE Section 11 T1S R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: EHLER #34-11-1

Location ID: 320309



Photo 1. Photo taken from the well location, facing Southeast. Photo illustrates all equipment has been removed. Well location has been left rough and did not observe any germination of desirable plant species. Appears the Operator has not seeded yet.



Inspection Photos

Location Name: EHLER #34-11-1

Location ID: 320309



Photo 2. Photo taken from the associated tank battery, facing West. See comments under Photo 1.



Inspection Photos

Location Name: EHLER #34-11-1

Location ID: 320309



Photo 3. Photo taken from the associated tank battery, facing South. See comments under Photo 1.

