

Inspection Photos
Location Name: Pole Gulch Unit 2
Location ID: 313420



Photo 1. Overview of location taken facing west. Annual weeds on location.



Photo 2. Old landfarm area.



Inspection Photos
Location Name: Pole Gulch Unit 2
Location ID: 313420



Photo 3. Wellhead sign obscured by vegetation. No bradenhead access apparent.



Photo 4. No bradenhead access apparent.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pole Gulch Unit 2
Location ID: 313420



Photo 5. Pit on location.



Photo 6. Tank battery.



Inspection Photos
Location Name: Pole Gulch Unit 2
Location ID: 313420



Photo 7. Incomplete tank label.



Photo 8. Incomplete tank label.

