

Inspection Photos
Location Name: Baggs Land & Cattle 1
Location ID: 312868



Photo 1. Overview of location taken facing west. Annual weeds on location.



Photo 2. No bradenhead access apparent.

Inspection Photos
Location Name: Baggs Land & Cattle 1
Location ID: 312868



Photo 3. Incomplete label on left hand tank.



Photo 4. Stained soil at tank bases.

