

Inspection Photos
Location Name: Pole Gulch 6
Location ID: 312865



Photo 1. Overview of location taken facing east. Annual weeds on location.



Photo 2. No bradenhead access apparent.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources