

# Final Reclamation Inspection

September 13, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320311

Inspection Document #: 697503257

Adams County, CO

SESW Section 13 T1S R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: N. COLORADO BLVD #24-13-8

Location ID: 320311



**Photo 1.** Photo taken from the southern associated offsite tank battery, facing North. Photo illustrates all equipment has been removed. The cut slopes and bermed areas have been seeded, as well as the working surface, but will remain in-process. It appears recent weed management (i.e., mowing) was performed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697503257



Inspection Photos  
Location Name: N. COLORADO BLVD #24-13-8  
Location ID: 320311



**Photo 2.** Photo taken from the southern associated offsite tank battery, facing West. See comments under Photo 1.



**Photo 3.** Photo taken from the associated offsite tank battery, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: N. COLORADO BLVD #24-13-8  
Location ID: 320311



**Photo 4.** Photo taken from the well location, facing Northwest. Photo illustrates a final land use change to housing development.



**Photo 5.** Photo taken from the well location, facing North. See comments under Photo 4.