

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location #: 462919



Photo #1

Little Lady 21 /South Well Pad

7: Wellsites

2: Producing | PR

5: Approved Permit to Drill | XX

Active: Not Drilled




Photo #2

Little Lady 22-1NH (05-123-49881) Well site

Producing | PR

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location #: 462919



Photo #3

Little Lady 22-2CH (05-123-49880) Wellsite

Producing | PR



Photo #4

Little Lady 22-1NH, 22-2CH

Battery site

Active

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location #: 462919



Photo #5

Little Lady 22-1NH, 22-2CH

Battery site

Active

Battery sign, Invalid Contact Number



Photo #6

Little Lady 22-1NH, 22-2CH

Battery site

ECD Pilot Fault, Not lit

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location #: 462919



Photo #7

Little Lady 22-1NH, 22-2CH

Battery site

ECD Pilot Fault, Not lit

Weeds



Photo #8

Little Lady 22-1NH, 22-2CH

Battery site

Active

Weeds around Tanks site

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location #: 462919



Photo #9

Little Lady 22-1NH, 22-2CH

Battery site

Separators

Weeds



Photo #10

Little Lady 22-1NH, 22-2CH

Battery site

Separators

Weeds

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location #: 462919



Photo #11

Little Lady 22-1NH, 22-2CH

Battery site

Flogistix Compressor

Weeds



Photo #12

Little Lady 22-1NH, 22-2CH

Battery site

Compressors

Weeds



Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location #: 462919



Photo #13

Little Lady 22-1NH, 22-2CH

Battery site

Compressors

Stained soil



Photo #14

Little Lady 22-1NH, 22-2CH

Battery site

Tanks: South side

Stained soil

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location #: 462919




Photo #15

Little Lady 22-1NH, 22-2CH

Wellsite

South & East of wells

Stained soil



Photo #16

Little Lady 22-1NH, 22-2CH

Battery site

Tanks: East side

Trash: rags

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location #: 462919



Photo #17

Little Lady 22-1NH, 22-2CH

Wellsite

South of wells

Unnecessary Equipment, items



Photo #18

Little Lady 22-1NH, 22-2CH

Battery site

Propane tank?

Contents, Hazard placards NOT posted