

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2021

Submitted Date:

09/15/2021

Document Number:

679604150

FIELD INSPECTION FORM

Loc ID 454899	Inspector Name: Santistevan, Brittani	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 7 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10669 Name of Operator: NICKEL ROAD OPERATING LLC Address: 44 COOK ST STE 705 City: DENVER State: CO Zip: 80206				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Lind, Jennifer		jennifer.lind@nickelroadoperating.com	Regulatory/Environmental Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454901	WELL	XX	06/18/2020		123-46773	DRAKE 2X-HNB-11-07-67	ND
454902	WELL	XX	06/18/2020		123-46774	DRAKE 2X-HC-11-07-67	ND
454903	WELL	XX	06/18/2020		123-46775	DRAKE 3X-HC-11-07-67	ND
454904	WELL	XX	06/18/2020		123-46776	DRAKE 1X-HC-11-07-67	ND
454905	WELL	XX	06/18/2020		123-46777	DRAKE 2X-HNC-11-07-67	ND
454906	WELL	XX	06/18/2020		123-46778	DRAKE 3X-HNB-11-07-67	ND
454908	WELL	XX	06/18/2020		123-46780	DRAKE 1X-HNB-11-07-67	ND
454909	WELL	XX	06/18/2020		123-46781	DRAKE 3X-HNC-11-07-67	ND
454910	WELL	XX	06/18/2020		123-46782	DRAKE 4X-HNB-11-07-67	ND
454911	WELL	PR	11/15/2019	OW	123-46783	DRAKE 4X-HNC-11-07-67	PR
454912	WELL	XX	06/18/2020		123-46784	DRAKE 4X-HC-11-07-67	ND
454913	WELL	PR	11/15/2019	OW	123-46785	DRAKE 5X-HC-11-07-67	PR
454914	WELL	PR	11/12/2019	OW	123-46786	DRAKE 5X-HNB-11-07-67	PR
454915	WELL	XX	06/18/2020		123-46787	DRAKE 5X-HNC-11-07-67	ND
454916	WELL	XX	06/18/2020		123-46788	DRAKE 6X-HC-11-07-67	ND
454917	WELL	XX	06/18/2020		123-46789	DRAKE 6X-HNB-11-07-67	ND
454918	WELL	XX	06/18/2020		123-46790	DRAKE 6X-HNC-11-07-67	ND
454919	WELL	XX	06/18/2020		123-46791	DRAKE 7X-HNB-11-07-67	ND
454920	WELL	XX	06/18/2020		123-46792	DRAKE 7X-HC-11-07-67	ND
454921	WELL	XX	06/18/2020		123-46793	DRAKE 8X-HNB-11-07-67	ND
454922	WELL	XX	06/18/2020		123-46794	DRAKE 8X-HNC-11-07-67	ND

454923	WELL	XX	06/18/2020		123-46795	DRAKE 8X-HC-11-07-67	ND
454924	WELL	XX	06/18/2020		123-46796	DRAKE 7X-HNC-11-07-67	ND

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Dead weeds on location. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	08/10/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 3	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 6	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	5	400 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities

Facility ID: 454901 Type: WELL API Number: 123-46773 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 454902 Type: WELL API Number: 123-46774 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 454903 Type: WELL API Number: 123-46775 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 454904 Type: WELL API Number: 123-46776 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 454905 Type: WELL API Number: 123-46777 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 454906 Type: WELL API Number: 123-46778 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 454908 Type: WELL API Number: 123-46780 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 454909 Type: WELL API Number: 123-46781 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 454910 Type: WELL API Number: 123-46782 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 454911 Type: WELL API Number: 123-46783 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 454912 Type: WELL API Number: 123-46784 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 454913 Type: WELL API Number: 123-46785 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 454914 Type: WELL API Number: 123-46786 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 454915 Type: WELL API Number: 123-46787 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 454916 Type: WELL API Number: 123-46788 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 454917 Type: WELL API Number: 123-46789 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 454918 Type: WELL API Number: 123-46790 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 454919 Type: WELL API Number: 123-46791 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 454920 Type: WELL API Number: 123-46792 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 454921 Type: WELL API Number: 123-46793 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 454922 Type: WELL API Number: 123-46794 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 454923 Type: WELL API Number: 123-46795 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 454924 Type: WELL API Number: 123-46796 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP TO PREVIOUS INSPECTION DOC#: 679604061. All previous corrective actions assigned to this location have not been resolved. All previous corrective actions have been re-assigned to this location with their original corrective action date. No new corrective actions were observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Tuesday, September 14, 2021 at approximately 15:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at DRAKE PAD (Nickel Road Operating), at location #: 454899 in WELD COUNTY Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. Dead weeds on location. It appears these were on location previously and have not been removed. Remove to comply with Rule 606. (Corrective Action Date: August 10, 2021) See attached photos #2-9.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	09/15/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604151	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533779