

Inspection Photos

Location Name: Abbott 10-43

Location ID: 320523



Pic 1 casing valve



Pic 2 Bradenhead exposed unable to open bradenhead valve.

Inspection Photos

Location Name: Abbott 10-43

Location ID: 320523

Sep 16, 2021 at 12:23:46 PM
39.969176,-104.530119
COGCC



Pic 3 location