

Inspection Photos

API: 071-06865

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06865 | Date: 9/16/2021

Inspection Photos



Photo 1. Facing northwest toward the access road. There is erosion along the road that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06865 | Date: 9/16/2021

Inspection Photos



Photo 2. Stormwater erosion of the access road is directed down toward the County Rd.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06865 | Date: 9/16/2021

Inspection Photos



Photo 3. Stormwater erosion is occurring further along the road as well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06865 | Date: 9/16/2021

Inspection Photos



Photo 4. Facing northwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06865 | Date: 9/16/2021

Inspection Photos



Photo 5. The water level is above freeboard at the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06865 | Date: 9/16/2021