

Inspection Photos

Location Name: Mojack USX /AB21-15

Location #: 420555




Photo #1

Mojack USX AB21-15 (05-123-32610) Wellsite

Temporarily Abandoned | TA

prior insp.



Photo #2

Mojack USX AB21-15, Faulk USX AB 21-16P, 21-10P

Battery site

Abandoned: ALL Equipment Removed

prior insp.