

Final Reclamation Inspection

August 25, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 332258

Inspection Document #: 701900068

Weld County, CO

CSE Section 29 T4N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mcleod 6
Location ID: 332258



Photo 1. 2019 aerial imagery the well head and access road (north is up). Note: the tank battery will be associated with well API # 123-24164.

Inspection Photos
Location Name: Mcleod 6
Location ID: 332258



Photo 2. Overview photo of well head, access road and reference area taken east of well head using a drone (north is right). Photo shows crop within the well head and along access road appear consistent with adjacent reference area.

Inspection Photos
Location Name: Mcleod 6
Location ID: 332258



Photo 3. Ground photo taken west of well pad looking east down access road.