

Final Reclamation Inspection

August 25, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323090

Inspection Document #: 701900073

Weld County, CO

NESE Section 20 T4N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 1. 2019 aerial imagery overview photo of the well head, tank battery and access road (north is up).

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 2. Well head overview photo taken from ground level at the north edge of the well head looking southwest. Crop had just been harvested, difficult to find a reference stalk. Overall, well head appeared consistent with adjacent reference area.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 3. Ground photos taken from the middle of the well head. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 4. Ground photos taken from the middle of the well head. Left photo facing south, right photo facing west.

Inspection Photos
Location Name:Peschel 43-20
Location ID: 323090



Photo 5. Tank battery overview photo taken from ground level at the western edge of the tank battery facing east.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 6. Ground photo taken from middle of the tank battery. Left photo is facing north, right photo facing east. Note: tank battery has seeded perennial grass.

Inspection Photos
Location Name:Peschel 43-20
Location ID: 323090



Photo 7. Ground photos taken from the middle of the tank battery. Left photo facing south, right photo facing west.