

Final Reclamation Inspection

August 25, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 307211

Inspection Document #: 701900077

Weld County, CO

SESW Section 25 T4N R68W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211




Photo 1. 2021 aerial imagery of the tank battery, well pad and access road (north is up).

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211




Photo 2. Overview photo of tank battery, well pad, access road and reference area using a drone (north is up).
Note: Stunted crop growth within well pad and tank battery disturbance pads.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 3. Tank battery overview photo taken at ground level from the western edge of the tank battery looking east. Note: majority of tank battery shows stunted alfalfa crop growth and more bare ground than adjacent reference area.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 4. Ground photos taken from the middle of the tank battery. Left photo is facing north, right photo is facing east.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 5. Ground photo taken from the middle of the tank battery. Left photo is facing south, right photo is facing west.