

Final Reclamation Inspection

August 25, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 331067

Inspection Document #: 701900078

Weld County, CO

NWSE Section 9 T5N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Edwards 33-9
Location ID: 331067



Photo 1. 2021 aerial imagery of well head, tank battery and access road (north is up).

Inspection Photos
Location Name:Edwards 33-9
Location ID: 331067



Photo 2. Well Pad overview photo taken at ground level from eastern edge of well pad looking west. Note: crop field had been processed recently.

Inspection Photos
Location Name: Edwards 33-9
Location ID: 331067



Photo 3. Ground photos taken from the middle of the well head disturbance pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name:Edwards 33-9
Location ID: 331067



Photo 4. Ground photos taken from the middle of the well head. Left photo facing south, right photo facing west.

Inspection Photos
Location Name: Edwards 33-9
Location ID: 331067



Photo 5. Reference photo taken from the western portion of the well head. Uncultivated rye crop remains and height appears consistent with adjacent reference crop area.