

Final Reclamation Inspection

August 26, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323104

Inspection Document #: 7019000087

Weld County, CO

NWSE Section 1 T4N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FHA 10-1
Location ID: 323104




Photo 1. 2016 aerial imagery of the well head, tank battery, and access road.

Inspection Photos
Location Name:FHA 10-1
Location ID: 323104




Photo 2. Overview photo of the well pad and reference area taken from the southwest edge of the well pad using a drone. Photo shows alfalfa crop within well head disturbance pad appears consistent with the rest of the crop field.

Inspection Photos
Location Name:FHA 10-1
Location ID: 323104



Photo 3. Tank battery overview photo taken at ground level from eastern edge of tank battery, looking west. Note: wheat crop appears to be processed and dead as opposed to just stunted. Significant bare batches throughout disturbance pad and patches of field bindweed present. Not representative of reference area.

Inspection Photos
Location Name:FHA 10-1
Location ID: 323104



Photo 4. Ground photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name:FHA 10-1
Location ID: 323104



Photo 5. Ground photos taken from the middle of the tank battery. Left photo facing south, right photo facing west.

Inspection Photos
Location Name:FHA 10-1
Location ID: 323104



Photo 6. Reference photo taken from middle of tank battery looking southwest down well pad access road. Note wheat crop heights just outside of tank battery disturbance pad and field bindweed (both designated with red arrows). Southern edge of tank battery highlighted in light blue