

Inspection Photos

API: 071-07687

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07687 | Date: 9/16/2021

Inspection Photos



Photo 1. Facing northwest toward the access road. The access road remains with gravel per approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07687 | Date: 9/16/2021

Inspection Photos



Photo 2. Facing northwest toward the location. Gravel pile remains per approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07687 | Date: 9/16/2021

Inspection Photos



Photo 3. Facing northeast at the location. Perennial vegetation has uniformly established to reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07687 | Date: 9/16/2021

Inspection Photos



Photo 4. Facing south at the location. Perennial vegetation has uniformly established to reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07687 | Date: 9/16/2021

Inspection Photos



Photo 5. Facing southwest at the location. Perennial vegetation has uniformly established to reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07687 | Date: 9/16/2021