

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26SWNW

Location ID: 334702



Photo #4917 from entrance to location.



Photo #4918 from entrance to location.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26SWNW

Location ID: 334702



Photo #4919 Glycol storage tank missing required information.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources