

Inspection Photos
Operator: Merrion
Facility: 067-09173
Date: 9/16/2021



Photo 1. View of new fence panels installed in the southern portion of the facilities area.



Photo 2. View of new fence panel installed in the northern portion of the facilities area.