

Inspection Photos
Operator: Simcoe
Facility: 067-06679
Date: 9/16/2021



Photo 1. View of the project area from the northwestern corner facing center. Kochia weeds (up to 3ft tall) need to be managed.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing in portions with western wheatgrass, smooth brome, and sand dropseed.



Photos 3-5. View of Russian knapweeds remaining within the interim reclamation areas. Approximately 300 individuals observed.






Photo 6. View of stormwater erosion and sediment deposition occurring on the well pad cut-slope.



Photo 7. View of pinyon and juniper woodland with understory of sagebrush, prickly pear, and squirreltail.