

Inspection Photos
Operator: Simcoe
Facility: 067-06644
Date: 9/16/2021



Photo 1. View of the project area from the well pad entrance facing center. Musk thistles appear to be treated.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with smooth brome, sand dropseed, and western wheatgrass.



Photo 3. View of kochia weeds up to 3ft tall growing along the edge of the working area.



Photo 4. View of more kochia growing adjacent to facilities.