


Inspection Photos

Location Name: UPRR 60 PAN AM E 2

Location ID: 320083

Sep 21, 2021 at 1:37:22 PM
39.987094,-104.529640
9005 E 160th Ave
Keenesburg CO 80643
United States
COGCC



Pic 1 workover rig rigging up.

Sep 21, 2021 at 1:42:54 PM
39.987064,-104.530435
Keenesburg CO 80643
United States
COGCC



Pic 2 rig crew now wearing FR clothing. Proximity of dog house to wellhead.