

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 1 – Sign at Entrance

Photo 2 – Pumping Unit

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 3 – Wellhead



Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 5 – Tank Battery



Photo 6 – Heater Treater

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 7 – Flare and ECD



Photo 8 – Lease Road looking South

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 9 – Lease Road looking South

Photo 10 – Lease Road looking South

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 11 – Lease Road looking South

Photo 12 – Lease Road looking West

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 13 – Lease Road looking West