

Inspection Photos
Location Name: Pergamos 1-8-41-7-60
Location ID: 428592



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: Pergamos 1-8-41-7-60
Location ID: 428592



Photo 3 – Stained Soil at Gas Engine



Photo 4 – Oily Waste at Gas Engine

Inspection Photos
Location Name: Pergamos 1-8-41-7-60
Location ID: 428592



Photo 5 – Stained Soil at Gas Engine



Photo 6 – ECD

Inspection Photos
Location Name: Pergamos 1-8-41-7-60
Location ID: 428592



Colorado Oil and Gas Conservation Commission
40.59598, -104.10944, 4809.8ft, 195°
09/14/2021 13:47:11

Photo 7 – Tank Battery



Colorado Oil and Gas Conservation Commission
40.59594, -104.10974, 4814.3ft, 184°
09/14/2021 13:47:24

Photo 8 – Tank Battery Sign

Inspection Photos
Location Name: Pergamos 1-8-41-7-60
Location ID: 428592



Photo 9 – Heater Treater