

Inspection Photos
Location Name: Shable 07-68HN
Location ID: 430742




Photo 1 – Wellhead



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Shable 07-68HN
Location ID: 430742



Photo 3 – Separators



Photo 4 – Tank Battery

Inspection Photos
Location Name: Shable 07-68HN
Location ID: 430742



Photo 5 – Tank Battery Sign




Photo 6 – Unmarked Risers at Compressor

Inspection Photos

Location Name: Shable 07-68HN
Location ID: 430742




Photo 7 – Gas Meter Calibration Card

Photo 8 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Shable 07-68HN
Location ID: 430742



Photo 9 – Weeds in Interim Reclamation Area



Photo 10 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Shable 07-68HN
Location ID: 430742



Photo 11 – Weeds in Interim Reclamation Area