

# Interim Reclamation Inspection

September 21, 2021

Operator: OVERLAND RESOURCES LLC - 19035

Location ID: 320748

Inspection Document #: 697503263

Arapahoe County, CO

SESW Section 16 T5S R62W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATE-CRAIG #2-16  
Location ID: 320748



**Photo 1.** Photo taken from the associated offsite tank battery, which is the subject complaint location. Photo illustrates the Operator sign.







**Photo 2.** Photo taken from the northern tank battery, facing Southwest. Photo illustrates unmanaged weeds throughout the entire tank battery, which include Russian thistle, Kochia and a List B Colorado noxious weed, Diffuse knapweed (red circle).



**Photo 3.** Close up photo of Diffuse knapweed.



Inspection Photos  
Location Name: STATE-CRAIG #2-16  
Location ID: 320748



**Photo 4.** Photo taken from the southern tank battery, facing Southeast. See comments under Photo 2.



**Photo 5.** Photo taken from the southern tank battery, facing West. Photo is illustrating mostly Diffuse knapweeds.



Inspection Photos  
Location Name: STATE-CRAIG #2-16  
Location ID: 320748



**Photo 6.** Photo taken from the southern tank battery, facing Northeast. See comments under Photo 2.



**Photo 7.** Photo taken from the northern tank battery, facing East. See comments under Photo 2.

Inspection Photos  
Location Name: STATE-CRAIG #2-16  
Location ID: 320748



**Photo 8.** COGCC GISOnline 2019 aerial imagery illustrates the complaint tank battery location (orange star). Facility and flowline layers are turned on and there is no reported off-location flowline information.

