

TEP
RGU 43-23
Location # 433287



location



location

TEP
RGU 43-23
Location # 433287



location



location



TEP
RGU 43-23
Location # 433287



Lack of labeling/ Glycol storage capacity stamp



Glycol storage capacity stamp



TEP
RGU 43-23
Location # 433287



Glycol storage dimensions



Glycol storage dimensions

TEP
RGU 43-23
Location # 433287



Glycol storage dimensions




Debris

TEP
RGU 43-23
Location # 433287




Debris



Debris

TEP
RGU 43-23
Location # 433287



Debris



Chemical pump leaking



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RGU 43-23
Location # 433287



Lack of stabilization/erosion



Debris



TEP
RGU 43-23
Location # 433287



Lack of stabilization/erosion



Lack of stabilization/erosion



TEP
RGU 43-23
Location # 433287



Lack of stabilization/erosion



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources