

Interim Reclamation and Stormwater Inspection

September 21, 2021

Operator: PAINTED PEGASUS PETROLEUM LLC - #10711

Location ID: 320155

Inspection Document #: 697503265

Adams County, CO

SWNW Section 2 T2S R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: VETTER 12-2 #1
Location ID: 320155



Photo 1. Photo taken from the tank battery. Photo illustrates Operator signs.

Inspection Photos
Location Name: VETTER 12-2 #1
Location ID: 320155



Photo 2. Photo taken from the southern tank battery, facing Southeast. Photo illustrates unmanaged weeds.



Photo 3. Photo taken from the southern tank battery, facing Northeast. See comments under Photo 2.



Inspection Photos
Location Name: VETTER 12-2 #1
Location ID: 320155



Photo 4. Photo taken from the northern tank battery, facing Northeast. Photo illustrates unmanaged weeds.



Photo 5. Photo taken from the northern tank battery, facing East. See comments under Photo 2.

Inspection Photos
Location Name: VETTER 12-2 #1
Location ID: 320155




Photo 6. COGCC GISOnline 2019 aerial imagery illustrates the tank battery location (red circle). Facility and flowline layers are turned on and there is no reported off-location flowline information.

