

Interim Reclamation and Stormwater Inspection

September 21, 2021

Operator: BEHRENS RESOURCES INC - #10695

Location ID: 320746

Inspection Document #: 697503267

Arapahoe County, CO

NWSE Section 16 T5S R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE-CRAIG #1-16
Location ID: 320746



Photo 1. Photo taken from the tank battery. Photo illustrates Operator sign which has not been updated.



Inspection Photos
Location Name: STATE-CRAIG #1-16
Location ID: 320746



Photo 2. Photo taken from the southern tank battery, facing Southwest. Photo illustrates unmanaged weeds.



Photo 3. Photo taken from the southern tank battery, facing Northwest. See comments under Photo 2.



Inspection Photos
Location Name: STATE-CRAIG #1-16
Location ID: 320746



Photo 4. Photo taken from the northern tank battery, facing East. See comments under Photo 2.



Photo 5. Photo taken from the northern tank battery, facing South. See comments under Photo 2.

