

# Interim Reclamation and Stormwater Inspection

September 21, 2021

Operator: BEHRENS RESOURCES INC - #10695

Location ID: 320643

Inspection Document #: 697503269

Arapahoe County, CO

NENE Section 8 T5S R62W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SCHMIDT #2  
Location ID: 320643



**Photo 1.** Photo taken from the tank battery. Photo illustrates Operator sign.





Inspection Photos  
Location Name: SCHMIDT #2  
Location ID: 320643



**Photo 2.** Photo taken from the northern tank battery, facing South. Photo illustrates unmanaged weeds.

Note- previous inspection on 7/28 stated to control weeds.



**Photo 3.** Photo taken from the northern tank battery, facing West. See comments under Photo 2.



Inspection Photos  
Location Name: SCHMIDT #2  
Location ID: 320643



**Photo 4.** Photo taken from the southern tank battery, facing South. See comments under Photo 2.



**Photo 5.** Photo taken from the southern tank battery, facing South. Photo illustrates equipment is not in good mechanical condition and is leaking.