

Final Reclamation Inspection

September 21, 2021

Operator: AXIS EXPLORATION LLC - #10646

Location ID: 320670

Inspection Document #: 697503279

Arapahoe County, CO

NENE Section 21 T4S R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: REEVES 41-21 #2
Location ID: 320670



Photo 1. Photo taken from the entrance of the well location access road, facing West.
Photo illustrates the access road is evident.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503279

Inspection Photos
Location Name: REEVES 41-21 #2
Location ID: 320670



Photo 2. Photo taken from the western access road, facing East. See comments under Photo 1.



Photo 3. Photo taken from the well location, facing West. A significant bare patch with undesirable plant species, including Common mullein.

Inspection Photos
Location Name: REEVES 41-21 #2
Location ID: 320670



Photo 4. Photo taken from the northern flowline removal area, facing South. The flowline between the well location and tank battery appear to be progressing towards final reclamation standards.



Photo 5. Photo taken from the southern flowline removal area, facing North. See comments under Photo 4.

Inspection Photos
Location Name: REEVES 41-21 #2
Location ID: 320670



Photo 6. Photo taken from the associated offsite tank battery, facing East. Photo illustrates no equipment was observed. Appears Operator might be plugging the last associated well.



Photo 7. Photo taken from the associated offsite tank battery, facing South. See comments under Photo 6.