

Inspection Photos

API: 071-09301

Operator: OGRIS OPERATING LLC

Inspection Date: 9/23/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09301 | Date: 9/23/2021

Inspection Photos



Photo 1. Facing southwest along the main road. There is rocks that have fallen into the road way.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 9/23/2021

Inspection Photos



Photo 2. The side of the main road is eroded and not stabilized. Lat/Long:37.10084,-104.789327.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 9/23/2021

Inspection Photos



Photo 3. Further along the main road. Stormwater has caused erosion along the roadside. This area may need a culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 9/23/2021

Inspection Photos



Photo 4. The side of the main road has eroded and is unstable. This area needs to be repaired and stabilized.



Inspection Photos



Photo 5. The cattle guard at Lat/Long:37.08881,-104.78996; is in disrepair.

