

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /27SESE

Location ID: 334113



Photo #4920 from entrance to location.



Photo #4921 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /27SESE

Location ID: 334113



Photo #4922 Glycol storage tanks missing required information.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources