

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOLVAY-67S96W /2NWSW

Location ID: 334726



Photo #4930 from entrance to location.



Photo #4931 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOLVAY-67S96W /2NWSW

Location ID: 334726



**Photo #4932 Glycol storage tank missing required information.**

