

Chaco Energy Company, Krause-Albin 1-20

005-06478

Inspection #688311295

8/30/2021

PA/Equipment/Reclamation Inspection



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.60527, -104.47083, 5761.2ft, 341°
08/30/2021 12:32:33 PM



Wellhead
area

Colorado Oil and Gas Conservation Commission
39.60544, -104.471, 5764.4ft, 281°
08/30/2021 12:32:55 PM



Wellhead
area
looking
to
treater
area

Colorado Oil and Gas Conservation Commission
39.60542, -104.47098, 5761.2ft, 309°
08/30/2021 12:32:45 PM

Tank
battery
area

Colorado Oil and Gas Conservation Commission
39.60545, -104.47102, 5764.4ft, 10°
08/30/2021 12:32:59 PM



Tank
battery
area

Colorado Oil and Gas Conservation Commission
39.6057, -104.47104, 5771.0ft, 49°
08/30/2021 12:33:26 PM



Treater
area, gas
sales
marker

Colorado Oil and Gas Conservation Commission
39.60572, -104.47137, 5767.7ft, 254°
08/30/2021 12:34:04 PM

Treater
area

Colorado Oil and Gas Conservation Commission
39.60569, -104.47153, 5764.4ft, 245°
08/30/2021 12:34:24 PM



Native vegetation

Colorado Oil and Gas Conservation Commission
39.71004, -104.2118, 251°
08/30/2021 12:34:56 PM