

Inspection Photos

API: 071-09178

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2021

Inspection Photos



Photo 1. Drone aerial photo facing west toward the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2021

Inspection Photos




Photo 2. Drone aerial photo facing northwest toward the reclaimed location. A berm is installed at red arrow which appears to be directed east with no stormwater control. This needs to be monitored and may require additional BMP's.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2021

Inspection Photos



Photo 3. Facing west down at the location. A large berm was installed at the bottom of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2021

Inspection Photos



Photo 4. Facing northeast toward the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2021

Inspection Photos



Photo 5. There appears to be signs of erosion in the area circled. This area may need additional BMP's to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2021

Inspection Photos



Photo 6. Facing east at the bottom of the location. A large berm was installed at the bottom with rock rip/rap.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2021

Inspection Photos



Photo 7. Facing east toward the reclaimed location. A berm is installed at red arrow which appears to be directed east with no stormwater control. This needs to be monitored and may require additional BMP's.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2021

Inspection Photos



Photo 8. Facing west toward the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2021