

Inspection Photos
Location Name: GreeneMeir 9-30
Location ID: 319876



Pic 1 Weeds unmanaged on location, unable to inspect equipment



Pic 2 weeds unmanaged on location unable to inspect equipment

Inspection Photos

Location Name: GreeneMeir 9-30

Location ID: 319876



Pic 3 Tanks Weeds unmanaged on location unable to inspect



Pic 4 Separator Weeds unmanaged unable to inspect

Inspection Photos

Location Name: GreeneMeir 9-30

Location ID: 319876

Sep 23, 2021 at 1:06:33 PM
39.933205,-104.586448
COGCC



Pic 5 Separator Weeds unamagaged unable to inspect

Sep 23, 2021 at 1:06:57 PM
39.933076,-104.586244
COGCC



Pic 6 pit Weeds unmanaged unable to inspect