

**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**



**Photo 1 WH sign**



**Photo 2 WH**

**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**



**Photo 3 Pump Jack**



**Photo 4 Ancillary equipment**



**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**



**Photo 5 Dead weeds in Pump Jack base**



**Photo 6 Dead weeds around Pump Jack base**

**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**



**Photo 7 Dead weeds in and around Pump Jack base**



**Photo 8 Dead weeds around Horizontal Heated Separator**



**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**



**Photo 9 Dead weeds around Horizontal Heated Separator**



**Photo 10 Flow line manifold**



**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**




**Photo 11 Dead weeds around Aux flow line engine**



**Photo 12 Gas Meter Run**



**Location ID: 311296**



**Photo 13 Card in meter box indicates that calibration is not current**



**Photo 14 Dead weeds in tank battery berm, TB sign**

**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**



**Photo 15 Dead weeds in and on tank battery berm**

**Photo 16 Dead weeds in and on tank battery berm**






**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**



**Photo 17 Dead weeds in and on tank battery berm**

**Photo 18 Dead weeds in and on tank battery berm**

**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**



**Photo 19 Dead weeds around PW vessel**

**Photo 20 Dead weeds in and on tank battery berm**



**Inspection Photos**  
**Location Name: Glen Horton #1**  
**Location ID: 311296**



**Photo 21 Stained concrete by Crude tank**



**Photo 22 Stained concrete by Crude tank**