

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2021

Submitted Date:

09/27/2021

Document Number:

696105078

FIELD INSPECTION FORMLoc ID 310695 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296522	WELL	SI	09/01/2017	OW	123-26818	WELLS RANCH AA 21-02	SI

General Comment:

This is a WELL / BATTERY inspection.

Well(s): 1: Shut-In | SI.

Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs
(310695, 310694).

(Well(s): 1: Shut-In | SI ; 1: Temporarily Abandoned | TA).

Centralized Battery formerly served 2 Location IDs
(310692, 310693).

(Well(s): 2: Plugged & Abandoned | PA).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 500px;" type="text"/>
Corrective Action:	<input style="width: 500px;" type="text"/> Date: <input style="width: 100px;" type="text"/>

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Iron pipe.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Iron pipe.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Iron pipe. Surrounded by earth berms.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Horizontal Heated Separator	# 2			
Comment:	Equipment formerly assigned to Location ID: 310692. Wells Ranch AA 21-01 well has been Plugged & Abandoned PA.			
Corrective Action:				Date:
Type: Pig Station	# 1			
Comment:	Equipment formerly assigned to Location ID: 310692. Wells Ranch AA 21-01 well has been Plugged & Abandoned PA.			
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:	Equipment formerly assigned to Location ID: 310692. Wells Ranch AA 21-01 well has been Plugged & Abandoned PA.			
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:	Crude storage vapor line combuster. Controls crude oil tanks vapors. Pilots: OFF Shut-down. Equipment formerly assigned to Location ID: 310692. Wells Ranch AA 21-01 well has been Plugged & Abandoned PA.			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Calibration card indicates NO calibration within last year. Last calibration: 12/13/2017. Inactive. No production. Equipment formerly assigned to Location ID: 310692. Wells Ranch AA 21-01 well has been Plugged & Abandoned PA.			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 2 Location IDs (310695, 310694). (Well(s): 1: Shut-In SI ; 1: Temporarily Abandoned TA). Centralized Battery formerly served 2 Location IDs (310692, 310693). (Well(s): 2: Plugged & Abandoned PA).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,	
Comment:				Equipment formerly assigned to Location ID: 310692. Wells Ranch AA 21-01 well has been Plugged & Abandoned PA.		
Corrective Action:				Date:		
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity) 53 Bbls.						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:				Shares berms w/ crude oil tanks.		
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		40.475810,-104.434950	
Comment:				Equalizer line connects crude oil tanks. Equipment formerly assigned to Location ID: 310692. Wells Ranch AA 21-01 well has been Plugged & Abandoned PA.		
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:				Shares berms w/ produced H2O vault.		
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No	NO					
Comment:						

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 296522 Type: WELL API Number: 123-26818 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
COGCC records indicate last production: 11/2015.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 05/18/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 09/27/2021 at approximately 16:24 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH AA-66N63W /21NWNE Location ID: 310695 Well Name(s): Wells Ranch AA 21-02. API: 05-123-26818. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (310695, 310694). (Well(s): 1: Shut-In SI ; 1: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 2 Location IDs (310692, 310693). (Well(s): 2: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/27/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105079	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5541500