

# Inspection Photos

9/24/2021

Operator: SG INTERESTS I LTD - 77330

Location ID: 428197

Gunnison County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



September 24, 2021  
39.04797023N 107.39144195W



September 24, 2021  
39.04796737N 107.39144134W

**Photo 1:** Photo provides overview of the Location. Interim reclamation of the location has commenced. Unclear if revegetation activities have been conducted.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 2:** Photo provides example of the interim areas of the Location; BMPs on interim areas are missing or insufficient to protect and stabilize soils; tracking has been implemented along the contour of the slopes, rather than up and down, and will facilitate stormwater erosion.

## Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 428197



**Photo 3:** Photos taken from the interim areas of the Location; BMPs to stabilize soils missing or insufficient.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



September 24, 2021

**Photo 4:** Photos shows cellar at wellhead has been backfilled.