

# Inspection Photos

9/24/2021

Operator: GUNNISON ENERGY LLC #10515

Location ID: 324464

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC #10515  
Location ID: 324464



**Photo 1:** Photo shows adequate, impervious containment has not been installed at the tanks in accordance with good engineering practices.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC #10515  
Location ID: 324464



September 24, 2021  
39.15627522N 107.47739726W



September 24, 2021  
39.15633488N 107.47751377W

**Photo 2:** Photo shows adequate, impervious containment has not been installed at the tanks in accordance with good engineering practices.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC #10515  
Location ID: 324464



**Photo 3:** Photos shows control measurers at the stockpiled soil has not been installed in accordance with good engineering practices.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC #10515  
Location ID: 324464



**Photo 4:** Photo shows example of unused equipment/trash/debris not necessary for production stored on the Location. Photo also shows barrel with inadequate spill prevention or containment BMPs

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC #10515  
Location ID: 324464



**Photo 5:** Photo taken from the northwest end of the Location. Photo shows various trash/debris/equipment being stored off-site of the Location.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC #10515  
Location ID: 324464



**Photo 6:** Photos taken from the north end of the Location. Photo shows areas requiring interim reclamation; interim reclamation has not been conducted in accordance with 1003 Rules and corrective actions.