

Inspection Photos
Location Name: R.S. Vincent Unit 1
Location ID: 318180



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: R.S. Vincent Unit 1
Location ID: 318180



Photo 3 Pump Jack

Photo 4 ancillary equipment

Inspection Photos
Location Name: R.S. Vincent Unit 1
Location ID: 318180



Photo 5 TB sign

Photo 6 TB

Inspection Photos
Location Name: R.S. Vincent Unit 1
Location ID: 318180




Photo 7 Gas Meter Run

Photo 8 Card in meter box indicates that calibration is not current

Inspection Photos
Location Name: R.S. Vincent Unit 1
Location ID: 318180



Photo 9 Horizontal Heated Separator

Photo 10 Flow line manifold