

Inspection Photos
Location Name: Hazel McHale #1
Location ID: 317719



Photo 1 weeds growing under WH sign

Photo 2 weeds growing around WH

Inspection Photos
Location Name: Hazel McHale #1
Location ID: 317719



Photo 3 Pump Jack



Photo 4 ancillary equipment

Inspection Photos
Location Name: Hazel McHale #1
Location ID: 317719



Photo 5 lease operator cutting weeds



Photo 6 Horizontal Heated Separator

Inspection Photos
Location Name: Hazel McHale #1
Location ID: 317719



Photo 7 Gas Meter Run




Photo 8 Card in meter box indicates that calibration is not current

Inspection Photos
Location Name: Hazel McHale #1
Location ID: 317719



Photo 9 PW vessel



Photo 10 Aux motor and flow line manifold

Inspection Photos
Location Name: Hazel McHale #1
Location ID: 317719




Photo 11 PW vessel



Photo 12 Aux motor and flow line manifold