

TEP  
Circle B 5  
Location # 334695



location



location

TEP  
Circle B 5  
Location # 334695



location



location



TEP  
Circle B 5  
Location # 334695



location



location

TEP  
Circle B 5  
Location # 334695



ECD not connected (storage of equipment)



South East corner of tank battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
Circle B 5  
Location # 334695



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**





TEP  
Circle B 5  
Location # 334695



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**

