

Inspection Photos
Location Name: State 3-X
Location ID: 324702



**Photo 1. Overview of location taken facing northwest.
Workover and associated equipment stored at wellhead.**



Photo 2. No bradenhead access apparent. Stained soil.

