

# Inspection Photos

API: 071-09111

Operator: OGRIS OPERATING LLC

Inspection Date: 9/28/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09111 | Date: 9/28/2021

## Inspection Photos



**Photo 1.** Facing southeast along the main access road. The erosion along the road needs to be repaired. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09111 | Date: 9/28/2021



## Inspection Photos



**Photo 2.** The cattle guard is filled in with sediment and needs to be repaired. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09111 | Date: 9/28/2021



## Inspection Photos



**Photo 3.** There is erosion along the side of the road which needs BMP's to prevent further erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09111 | Date: 9/28/2021



## Inspection Photos



**Photo 4.** There is erosion along the side of the road which needs BMP's to prevent further erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09111 | Date: 9/28/2021



## Inspection Photos



**Photo 5.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09111 | Date: 9/28/2021



## Inspection Photos



**Photo 6.** There is a dripping water leak at the wellhead which has not been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09111 | Date: 9/28/2021