

Inspection Photos

API: 071-08749

Operator: OGRIS OPERATING LLC

Inspection Date: 9/28/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08749 | Date: 9/28/2021

Inspection Photos



Photo 1. Facing northeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08749 | Date: 9/28/2021

Inspection Photos



Photo 2. There is a dripping water leak at the wellhead causing water to spill across the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08749 | Date: 9/28/2021

Inspection Photos



Photo 3. The sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08749 | Date: 9/28/2021